

Columbia Heights/Mount Pleasant Transportation Study

final report

prepared for

District Department of Transportation

prepared by

Cambridge Systematics, Inc.

with

Daniel Consultants, Inc.
Chance Management Advisers, Inc.

final report

Columbia Heights/Mount Pleasant Transportation Study

prepared for

District Department of Transportation

prepared by

Cambridge Systematics, Inc.
4445 Willard Avenue, Suite 300
Chevy Chase, Maryland 20815

January 2004

Table of Contents

Executive Summary	ES-1
1.0 Assessment of Existing Conditions	1-1
1.1 Introduction	1-1
1.2 Demographics and Land Use	1-3
1.3 Existing Traffic Characteristics.....	1-6
1.4 Pedestrian/Bicycle Issues	1-19
1.5 Transit	1-24
1.6 Parking.....	1-29
1.7 Conclusion.....	1-36
2.0 Recommended Transportation Improvements	2-1
2.1 Traffic	2-2
2.2 Transit	2-18
2.3 Pedestrian.....	2-22
2.4 Bicycle	2-29
2.5 Parking.....	2-33
2.6 Issues for Further Study	2-37
2.7 Summary	2-38

List of Tables

1.1	Proposed Developments in Study Area	1-5
1.2	Vehicle Classification Counts – 14 th Street at Irving Street.....	1-7
1.3	Origin of Traffic in Study Area.....	1-11
1.4	Definition of Level of Service.....	1-12
1.5	Columbia Heights Metrorail Station Ridership	1-24
1.6	WMATA Metrobus Route and Service Frequency	1-26
1.7	WMATA Metrobus Ridership	1-27
1.8	Parking Inventory – Metered Regulations.....	1-31
1.9	Parking Inventory – Residential Parking Regulations	1-31
1.10	Parking Inventory – Timed Parking Regulations	1-32
1.11	Parking Inventory – Bus Zone Regulations	1-32
1.12	Parking Survey Indicators – Thursday Midday.....	1-33
1.13	Parking Survey Indicators – Wednesday and Thursday Evening.....	1-34
1.14	Parking Survey Indicators – Saturday Midday.....	1-34
2.1	Parking Demand for New Development	2-33

List of Figures

1.1	Study Area Map.....	1-2
1.2	Commuting Mode	1-4
1.3	Study Area Traffic Volumes.....	1-8
1.4	14 th Street – Southbound Weekday	1-9
1.5	14 th Street – Northbound Weekday	1-10
1.6	Irving Street – Eastbound Weekday	1-10
1.7	Congestion and Level of Service <i>A.M. Peak</i>	1-14
1.8	Congestion and Level of Service <i>P.M. Peak</i>	1-15
1.9	Congestion and Level of Service <i>Weekend Midday</i>	1-16
1.10	Automobile Crashes 1999-2001.....	1-18
1.11	Pedestrian Street Crossings <i>Estimated 24-Hour Counts</i>	1-20
1.12	Pedestrian Crashes and Potential Safety Issue Areas 1997-2001	1-22
1.13	Mode of Access to Columbia Heights Metrorail Station	1-25
1.14	Bus Shelter Needs Assessment	1-28
1.15	Core Area Parking Regulations	1-30
2.1	Traffic Recommendations	2-3
2.2	Delays at 16 th /Park.....	2-4
2.3	Cars Blocking the “Box” at 14 th /Monroe.....	2-5
2.4	Recommendation – 14 th /Monroe (<i>Alternative 1</i>)	2-6
2.5	Recommendation – 14 th /Monroe (<i>Alternative 2</i>)	2-7
2.6	Recommendation – 14 th /Park/Kenyon.....	2-9

List of Figures (continued)

2.7	Recommendation – 16 th /Park/Pine.....	2-11
2.8	Physical Barrier for Pedestrians Along 16 th Street.....	2-11
2.9	15 th /16 th Merge.....	2-13
2.10	Recommendation – 16 th /15 th /Irving (<i>Alternative 1</i>)	2-14
2.11	Recommendation – 16 th /15 th /Irving (<i>Alternative 2</i>)	2-15
2.12	Adams Mill Road/Kenyon	2-16
2.13	Example of Alley Traffic Calming.....	2-18
2.14	Transit Recommendations.....	2-19
2.15	Consolidate Bus Stops.....	2-21
2.16	Pedestrian Recommendations	2-23
2.17	Recommendation – 16 th /Mt. Pleasant	2-25
2.18	Bulb-Outs (courtesy of Public Realm Forum)	2-27
2.19	Pedestrian Striping not Visible at 14 th /Irving.....	2-29
2.20	Bicycle Recommendations.....	2-30
2.21	Recommendation – Mt. Pleasant Street.....	2-31
2.22	14 th Street Bicycle Lanes.....	2-32